





Blyton

Timber effect planks with veining, available in seven neutral wood shades, each with a V3 high shade variation for an authentic look.





















NAT

TMMN32171 NAT/ AS

TMMN32173 NAT/ AS

NAT

TMMN46219 NAT/ AS


NAT/ AS

TMMN46220 TMMN46221 NAT/ AS

NAT (R10) / AS (R11)

	Sizes (mm)	> <	TMMN32174	TMMN32171	TMMN32171AS	TMMN32171THK	TMMN32173	TMMN32173AS	TMMN32173THK	TMMN32172	TMMN46219	TMMN46219AS	TMMN46220	TMMN46220AS	TMMN46221	TMMN46221AS	4 5
1	300x1200	9.5mm		1							1969		13		13		
2	300x1200 THK	20mm				1											6 7
3	200x1200	9.5mm		1	31			0			35				13	13	
4	50x50 MOS on 300x300 MESH	9.5mm		1	21								19	19	13	16	
5	72x338 CHEV on 292x338	9.5mm		1													
6	200x1200x40 ST	9.5mm	1	1									16		139		
7	50x1200 SK	9.5mm		20			10				30				13		







Blyton



Above Floor: TMMN32173THK

Right

Floor: TMMN32174 Wall: TMMN3217CHEV, TMMN3217MOS





Above

Floor: TMMN46219



Blyton

Technical data sheet - ISO 10545 average values

2	Dimension and surface quality	Conforms
3	Water absorption	Conforms
4	Flexural strength Breaking strength	50 N/mm2 3200 N
6	Deep abrasion resistance	<150mm3
8	Linear thermal expansion	<9 (MK)-1
9	Thermal shock resistance	Resistant
12	Frost resistance	Resistant
13	Chemical resistance	Unaffected
14	Stain resistance	Class 5
	Slip resistance	NAT R10 AS R11

Sustainability information





Cleaning and maintenance advice

Initial washing

The initial washing is fundamental for good treatment results. The initial washing is aimed at removing any laying residues and building grime.

Product: Deterdek Pro

Routine maintenance

The aim of the routine maintenance is to remove dirt and scuff marks. Must be carried out regularly. Product: Cleaner Pro

Special maintenance

Special maintenance is carried out in case of very stubborn dirt, when the routine maintenance is not enough to restore the original look of the surface.

Product: PS/87 Pro

Please see www.filasolutions.com for methods of use, dilution and coverage.