

VACO


- Industrial glass look
- Random mix of tile designs in each colour
- Suitable for internal wall applications

4
COLOURS

1
FINISHES

1
TILE SIZES

www.grestec.co.uk | T: 0345 130 2241 | E: sales@grestec.co.uk



DIL43285



DIL43286



DIL43287



DIL43288


* RANDOM MIX OF TILE DESIGNS IN EACH COLOUR

1



	SIZES (mm)	> <	FINISHES
1	200x200	6.5mm	GLAZED

SWATCH COLOURS MAY VARY, SAMPLES SHOULD BE REQUESTED. FIND US ON: [Instagram](#) [Pinterest](#) [Twitter](#) [LinkedIn](#)



TECHNICAL SPECIFICATION

TECHNICAL CHARACTERISTIC	STANDARD	AVERAGE VALUES	
Water absorption	ISO 10545-3	~16%	
Sizes	ISO 10545-2	Length and width	+/- 0.5%
		Thickness	+/- 5%
		Warpage of edges	+/- 0.3%
		Wedging	+/- 0.4%
		Warpage	+/- 0.3%
Modules of rupture	ISO 10545-4	22N/mm ²	
Thermal expansion coefficient	ISO 10545-8	8x10 ⁻⁶ °C ⁻¹	
Resistance to thermal shock	ISO 10545-9	Guaranteed	
Crazing resistance	ISO 10545-11	Guaranteed	
Resistance to chemical products	ISO 10545-13	Conforms	
Resistance to staining	ISO 10545-14	Conforms	

CLEANING + MAINTENANCE ADVICE

INITIAL WASHING

The initial washing is fundamental for good treatment results. The initial washing is aimed at removing any laying residues and building grime.

Equipment	Cloth
Procedure	<ul style="list-style-type: none"> • Clean off cement stains from grouting and other building work, which once hardened, will not be removed during any normal cleaning procedure. • Clean wall tiling with a dry cloth when joints are hard.

ROUTINE MAINTENANCE

The aim of the routine maintenance is to remove dirt and scuff marks. Must be carried out regularly.

Product	Filacleaner (Diluted 1:50 in warm water)
Equipment	Cloth
Procedure	<ul style="list-style-type: none"> • Remove dust with a dry cloth • Wash with FilaCleaner using a cloth that should be soaked often in the solution and wrung out well